

Oil Field Environmental Incident Summary

Incident: 20160317092438

Date/Time of Notice: 03/17/2016 09:24

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: BENTSON 24-13-161-98H 1XB

Field Name: WHITEAKER

Well File #: 22124

Date Incident: 3/17/2016

Time Incident: 07:30

Facility ID Number:

County: DIVIDE

Twp: 161

Rng: 98

Sec: 25

Qtr: NE NE

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer

PO BOX 7168

BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	barrels
Brine	1.5	Barrels	1	Barrels	1	barrels
Other					0	barrels

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/22/2016

Clean Up Concluded: 3/20/2015

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

The well was shut in, the treater was drained and vac truck called to clean up water off ground.

Wastes Disposal Location: Recovered salt water and contaminated soil to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 3/17/2016 **Status:** Reviewed - Assigned to Other Agency

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 1.5 barrels of brine were contained within the facility diking. NDIC retains oversight.